



SERVICE BULLETIN

BT100 Advisory Bulletin

Date: July 5, 2023
Bulletin Number: SB2023-001
Products: BT100 Series of Beacon Testers
Affected Serial Numbers: ALL

Description:

WS Technologies Inc. is advising customers that the above BT100 series of Beacon Testers are not recommended for measuring or decoding the following:

- **RLS (Return Link Service)**
- **ELT(DT)**
- **SGB (Second Generation Beacons)**
- **AIS (EPIRB)**

The BT200 and STB100 series of Beacon Testers are the recommended replacements. Please contact support@wst.ca if you have any questions.

Bill Street
President
WS Technologies Inc.